



CPWSD #1 of Schuyler County

P.O. Box 295

Queen City Mo 63561

660-766-2497

[cpwsd@nemr.net](mailto:cpwsd@nemr.net)

Dear CPWSD # 1 of Schuyler Co Customer

Our public water system is conducting a lead service line inventory. In performing the lead service line inventory, we need to know the material composition of both the publicly owned (water system-owned) and privately owned (customer-owned) portions of the service line. We are requesting your help in this identification process. Service lines can be made of many materials, such as plastic, copper, PEX, HDPE, galvanized, lead, etc. To complete our inventory, we are required to record the material composition of your service line, even if it is not made of lead. The material type must be reported to the Missouri Department of Natural Resources (MoDNR) as required by regulation. When reporting to MoDNR, we are required to provide the material of our portion of the service line as well.

There are several ways you can identify your service line material:

- If you had your service line installed or replaced and remember when, and what it is made of, you can let us know. If you have a record of what the service line is made of, such as an invoice from the person who performed the installation or replacement, that would be even better.
- The age of your home may indicate if a lead service line is present. The lead ban in Missouri was effective Jan. 1, 1989. The ban prohibited the use of lead in potable water applications after this date. If your home's construction was after the lead ban, most likely the service line is not lead.
- If you don't know the material composition of your service line, you can perform a visual inspection. The performance of a visual inspection starts where the service line enters your home. This is normally where it enters through the foundation or basement wall. Plastic, such as PVC, HDPE, PEX, etc., is easy to identify because most people have encountered it in the past. When new, copper appears shiny, like a new penny and green when older and weathered. Galvanized pipe appears as silver-gray when newer and gray to rusty when old. Lead appears as gray to a blue-gray color, and when scratched, lead becomes shiny like a new nickel. A magnet will not stick to lead but will stick to steel. Lead service lines can also have a wiped lead joint or bulb at locations where it attaches to other metals, or fittings which look like a snake that just ate something. You can use these techniques to identify your service line material. We can provide pictures of what these materials look like upon request, or you can go to the MoDNR website and access the web page that specifically addresses lead service line inventories at [dnr.mo.gov/water/business-industry-other-entities/technical-assistance-guidance/lead-service-lines](http://dnr.mo.gov/water/business-industry-other-entities/technical-assistance-guidance/lead-service-lines).
- If you are renting, you can ask the owner or manager what the service line material is. They can use the same techniques listed above to make a materials determination if they don't know.
- With your permission, we can help you investigate to determine the material used for your service line.

Please contact us to report your service line material or to request our help identifying your service line material. The lead service line inventory is a huge undertaking for our water system and your help is greatly appreciated.